



PFERD Grinding point POLINOX PNG aluminum oxide A

These tools are particularly used for surface work.

Abrasive: A = Aluminium oxide SiC = Silicon carbide - The non-woven abrasive flaps are arranged radially. A long tool life is achieved through the dense packing of the flaps.

Disclaimer: The content of this document has been composed with the utmost care. However, it is possible that certain information changes over time, becomes inaccurate or incomplete. ERIKS does not guarantee that the information provided on this document is up to date, accurate and complete; the information provided is not intended to be advice. ERIKS shall never be liable for damage resulting from the use of the information provided.